

Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7




FIG. 9

FIG. 9 is a detailed perspective view of the mechanical assembly. It shows the housing 4, the curved member 4', and the various internal components and joints labeled with numbers 11, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, and 64. The diagram illustrates the complex arrangement of parts and their interconnections, including the hinge mechanism at the bottom left and the various linkages and pivots throughout the assembly.




Fig 10




Fig. 11




Fig 12




Fig. 13

